

NO. 9 FOAMING BORE CLEANER - HOPPE'S NO. 9 FOAMING BORE CLEANER 12OZ

[Gun Cleaning & Chemicals](#) > [Solvents & Degreasers](#) > [Bore Solvents](#)

This 62-piece kit contains everything new and experienced shooters need to keep their firearm spotlessly clean. Traditional Hoppe's No. 9 Bore Cleaner, Lubricating Oil and components for keeping pistols, rifles and shotguns clean are contained in the durable carrying case. Kit includes: Hoppe's No.9 Gun Bore Cleaner, 2oz. Hoppe's Lubricating Oil, 2.25oz 6 Solid Brass Rods 14 Bronze Brushes 9 Mops Quickly and effortlessly dissolves and removes copper and powder residue. Its superior cleaning formula does the work for you, no brushing or other mechanical cleaning necessary. One-Step No Harsh Scrubbing Color Change Effectiveness Indicator Directions: Allow barrel to cool 5 minutes before use. Shake can well. Spray foam from chamber to muzzle Wait 15-30 minutes for foam to clean. Using a Hoppe's cleaning rod and patch, remove foam from barrel. Note: Foam will turn blue indicating copper removal or black indicating powder removal. 13 Spear Pointed Jags 4 Slotted Patch Loops 3 Utility Brushes 3 Muzzle Guards 3 Rod Adapters 25 Patches Hard Storage Case



This 62-piece kit contains everything new and experienced shooters need to keep their firearm spotlessly clean. Traditional Hoppe's No. 9 Bore Cleaner, Lubricating Oil and components for keeping pistols, rifles and shotguns clean are contained in the durable carrying case. Kit includes: Hoppe's No.9 Gun Bore Cleaner, 2oz. Hoppe's Lubricating Oil, 2.25oz 6 Solid Brass Rods 14 Bronze Brushes 9 Mops Quickly and effortlessly dissolves and removes copper and powder residue. Its superior cleaning formula does the work for you, no brushing or other mechanical cleaning necessary. One-Step No Harsh Scrubbing Color Change Effectiveness Indicator Directions: Allow barrel to cool 5 minutes before use. Shake can well. Spray foam from chamber to muzzle Wait 15-30 minutes for foam to clean. Using a Hoppe's cleaning rod and patch, remove foam from barrel. Note: Foam will turn blue indicating copper removal or black indicating powder removal. 13 Spear Pointed Jags 4 Slotted Patch Loops 3 Utility Brushes 3 Muzzle Guards 3 Rod Adapters 25 Patches Hard Storage Case

Attributes

- Name: [HOPPE'S NO. 9 FOAMING BORE CLEANER 12OZ](#)
- Manufacturer: [HOPPE'S](#)
- Product no.: 100046095
- Mfr. No.: 908
- Size: 12 oz
- Delivery weight: 0.422kg
- Shipping height: 76mm
- Shipping width: 76mm
- Shipping length: 210mm
- UPC: 026285009088

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [NO. 9 FOAMING BORE CLEANER SAFETY INSTRUCTIONS](#)
- [About Us](#)

NO. 9 FOAMING BORE CLEANER SAFETY INSTRUCTIONS

Introduction

Thank you for choosing the NO. 9 Foaming Bore Cleaner. This product is designed to help you maintain your firearms effectively and safely. Please read this safety instruction guide carefully to ensure safe and proper use of the product.

General Safety Guidelines

- Always follow the manufacturer's instructions for use.
- Ensure that the product is kept out of reach of children and pets.
- Use the product in a wellventilated area to avoid inhalation of fumes.
- Do not use the product near open flames or high heat sources.
- Wear appropriate personal protective equipment (PPE), such as gloves and safety goggles, when using the product.
- If the product comes into contact with skin or eyes, rinse immediately with plenty of water and seek medical advice if necessary.
- Report any unsafe products or accidents to the relevant authorities.

Specific Safety Precautions for Use

- **Flammability:** The foam may be flammable. Keep away from heat, sparks, and open flames.
- **Inhalation:** Avoid inhaling the foam or vapors. Use in a wellventilated area.
- **Skin Contact:** Avoid prolonged contact with skin. Wear gloves to prevent irritation.
- **Eye Contact:** Avoid contact with eyes. Use safety goggles if necessary.
- **Storage:** Store in a cool, dry place away from direct sunlight and heat sources. Ensure the cap is tightly secured when not in use.

Instructions for Installation and Usage

1. **Preparation:** Allow the firearm barrel to cool for at least 5 minutes before using the cleaner.
2. **Shake the Can:** Shake the can well to ensure the foam is properly mixed.
3. **Application:**
 - Point the nozzle towards the chamber of the firearm.
 - Spray the foam from the chamber to the muzzle.
4. **Wait:** Allow the foam to work for 1530 minutes. The foam will change color to indicate the type of residue being cleaned (blue for copper, black for powder).
5. **Cleaning:**
 - Using a Hoppe's cleaning rod and patch, remove the foam from the barrel.
6. **PostUse:** After cleaning, ensure that the firearm is thoroughly dried and lubricated as needed.

Disposal Instructions

- Dispose of empty cans according to local regulations for hazardous waste.
- Do not puncture or incinerate the can, even when empty.
- Ensure that any leftover product is disposed of safely and in accordance with local guidelines.

Contact Information for Further Support

For any safety inquiries or concerns regarding this product, please reach out to the manufacturer or your local regulatory authority. Always check for updates on product recalls or safety alerts through the EU Safety Gate

platform.

Thank you for your attention to these safety instructions. Enjoy using the NO. 9 Foaming Bore Cleaner safely and effectively!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk