

FULL METAL JACKET 30 CALIBER (0.308") FULL METAL JACKET BULLETS - FULL METAL JACKET 30 CALIBER (0.308") 150GR BOATTAIL 100/BOX

[Reloading](#) > [Bullets](#) > [Rifle Bullets](#)

The thin-plated full metal jacket offered by other manufacturers is easily distorted and often breaks or separates when the bullet impacts the target. The Hornady AMP bullet jacket features virtually zero tolerance for concentricity and near-zero wall thickness variation, punching through targets without deforming or breaking.



Attributes

- Name: [FULL METAL JACKET 30 CALIBER \(0.308"\) 150GR BOATTAIL 100/BOX](#)
- Manufacturer: [HORNADY](#)
- Product no.: 749003266
- Mfr. No.: 3037
- Ballistic Coefficient (G1): 0.398
- Brand Style: Full Metal Jacket
- Bullet Style: Full Metal Jacket (FMJ)
- Caliber: 30 Caliber
- Diameter (Breech): 0.308
- Diameter (in): 0.308
- Grain: 150
- Sectional Density: 0.226
- Quantity: 100
- Delivery weight: 1.021kg
- Shipping height: 56mm
- Shipping width: 66mm
- Shipping length: 107mm
- UPC: 090255230376

Item details

Made in USA

US export classification: 0A505.x

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for FULL METAL JACKET 30 CALIBER \(0.308"\) BULLETS](#)
- [About Us](#)

Safety Instruction Guide for FULL METAL JACKET 30 CALIBER (0.308") BULLETS

Introduction

Thank you for choosing Hornady FULL METAL JACKET 30 CALIBER (0.308") bullets. This guide provides important safety instructions to ensure the safe use and handling of this product. Please read this guide carefully before use.

General Safety Guidelines

- Always handle ammunition with care and treat it as if it is loaded.
- Store ammunition in a cool, dry place, away from direct sunlight and moisture.
- Keep ammunition out of reach of children and unauthorized persons.
- Use appropriate personal protective equipment (PPE) such as safety glasses and hearing protection when shooting.
- Ensure that your firearm is in good working condition and is suitable for the caliber of ammunition being used.
- Follow all local laws and regulations regarding the use and storage of ammunition.

Specific Safety Precautions for Use

- Do not use this ammunition in firearms that are not specifically chambered for 30 Caliber (0.308").
- Inspect each cartridge for any signs of damage or defect before use. Do not use damaged cartridges.
- Avoid using ammunition that has been exposed to extreme temperatures or humidity.
- Do not attempt to modify or reload this ammunition.
- If a cartridge does not fire, wait at least 30 seconds before attempting to remove it from the chamber.

Instructions for Installation and Usage

- Ensure the firearm is pointed in a safe direction before loading.
- Open the action of the firearm and visually inspect the chamber to ensure it is clear of any obstructions.
- Load the ammunition into the magazine or chamber according to the firearm's manufacturer instructions.
- Close the action of the firearm securely.
- When ready to fire, align your sights on the target and squeeze the trigger gently.
- After firing, ensure the firearm is unloaded before handling or cleaning.

Disposal Instructions

- Dispose of any unused or damaged ammunition in accordance with local regulations.
- Do not throw ammunition in the trash or discard it in any manner that could pose a risk to others.
- Contact local law enforcement or hazardous waste disposal services for guidance on proper disposal methods.

Contact Information for Further Support

For any questions or safety inquiries regarding this product, please reach out to your local Hornady representative or authorized dealer.

Conclusion

By following these safety instructions and guidelines, you can help ensure a safe and enjoyable experience with your Hornady FULL METAL JACKET 30 CALIBER (0.308") bullets. Always prioritize safety when handling

ammunition and firearms. Thank you for your attention to these important safety practices.

About Us

Brownells Česká republika

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.cz